

Vista Apartments.

About the project.

Brymor were originally asked to assist with some exploratory works after reports of defects in the cladding of the Vista Apartments Building that was constructed by another contractor. Following which a complete scaffold was erected to safely protect the panels that were exposed to high winds.

We were subsequently awarded a contract to remove the existing cladding system and re-instate it with new cladding panels, insulation and breather membrane. The fire barriers were also replaced and upgraded to meet current regulations.

Defects in the existing carrier frame were repaired and recorded to enable the Client to form part of their claim against the original builder.

As the building was in occupation for the full period of the works, care had to be taken to ensure that the tenants were not inconvenienced too much.

Quality records were important with each cladding panel given a unique reference number. Photos and records were made at every stage of the process to demonstrate works undertaken. A total of more than 50,000 photos were taken and issued to the Client for record purposes.

Finally, as the scaffold was stripped, balconies were investigated, and as a result all the bolts had to be replaced.



CLIENT

Aviva Investors Global Services Ltd

LOCATION

Fratton Way, Fratton, Portsmouth

VALUE

£4.9M

DATE

December 2017 February 2019

